

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO.: 7,315,439

APPLICATION NO.: 10/797,241

ISSUE DATE: January 1, 2008

INVENTOR(S): Mark Muenzer; Reinhold Bayerer; and Peter Kanschat

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the cover page the Assignee information should be as follows:

-- (73) Assignee: EUPEC ~~Europäische~~ Europäische Gesellschaft für
Leistungshalbleiter ~~m&H GmbH & Co. KG~~ --

On the cover page the Foreign Application Priority Data should be as follows:

-- Jul. 10, 2002 (DE) 102 31 198.6 402-34-198

In the claims, column 10, line 67 should be as follows:

-- stage of a gate driver connected to the control terminal; --

In the claims, column 12, line 2 should be as follows:

-- wherein the a current gradient in the freewheeling device --

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Coats & Bennett, PLLC
1400 Crescent Green, Ste. 300
Cary, NC 27518

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.